








## How to Position a 3D model within the working area?

Unleash your Router's 3D Capabilities

- Import a model from the "3D Models" folder.



- Click the edge of the 3D model to highlight it in red and while clicking it move slightly so the black dash line appears as shown on the right here. Keep holding your click.
- At the same time moving the 3D model hold the **F2** Key. The "Accurate positioning" window pops up.
- Select the "Move to" option to enter accurate position as shown below:



Note the bottom left corner point selected defines which corner of the 3D model will be moved as a reference. The result here in the working Area when XYZ are set to 0.

